

FIG. 1





FIG. 2




FIG. 3




FIG. 4









FIG. 8










FIG. 12




FIG. 13




FIG. 14



FIG. 15






FIG. 16






- HALF KNOT
- ENTRY (IN)
- EXIT (OUT)
- HALF KNOT WITH WRAP AROUND
- SINGLE KNOT
- SUTURE BEADING (4 SQUARE KNOTS)

FIG. 17



FIG. 18



- HALF KNOT
- ENTRY (IN)
- EXIT (OUT)
- HALF KNOT WITH WRAP AROUND
- SINGLE KNOT
- SUTURE BEADING (4 SQUARE KNOTS)

FIG. 19




FIG. 20




FIG. 21




FIG. 22






FIG. 25




FIG. 27




FIG. 28




FIG. 29







FIG. 30



17/19




FIG. 31

FIG. 32





FIG. 33

FIG. 34




FIG. 35

